

GenesisFour Corporation

Estimate: 1124

Name	Danger, Nick	Company		Created Time	10/22/00 2:18 AM	Year	1985
Address	10 Any Street Apt# 10 Detroit, MI 90234	Address 2		Advisor	Adam	Make	BMW
Home	800-555-1110	Hat#		Division	DM	Model	325i
Work	800-555-1111	VIN	WBAAV33441FU96471	PO#		Lic#	3RD-EYE
Fax	800-555-1112	EngineData	2.5 6CYL	Page#	1 of 1	Fleet#	Automatic
						Color	White

Job Description

Replace failed timing belt

Remove valve cover; & inspect valve train.
Check cam tensioner & replace if needed.
Replace timing belt & pulley.
Reassemble & set valve clearances; replace valve cover gasket.
Road test then re-inspect for any leakage - all OK.
Note: Timing belt should be replaced every 60,000 miles or 4 years, whichever is soonest.

Line Total	418.56
Labor	292.50
Parts	126.06
Sublets	0.00

Part Number	Description	QTY	Each	Total
11 14 1 740 845	Timing Cover Gasket	1	6.70	6.70
11 31 1 469 240	Timing Belt	1	18.42	18.42
11 31 2 241 090	Tension Roller, Timing	1	100.94	100.94

Replace rear brakes.

Check for pedal feel and brake pull before & after.
Replace rear pads & rotors; adjust handbrake.

Line Total	558.60
Labor	292.50
Parts	266.10
Sublets	0.00

Part Number	Description	QTY	Each	Total
34 11 1 119 177	Brake Pad	1	50.60	50.60
34 21 1 152 095	Rotor (Disc), Rear	2	102.50	205.00
Hydraulic Fluid		1	8.50	8.50
Envir Disp Fee		2	1.00	2.00

Oil Service & 10-Point Safety Inspection

Road test to warm engine.
Drain & inspect engine oil; report any unusual color or texture.
Replace oil filter & oil: use synthetic if synthetic in use already.
Check engine coolant level, appearance, & protection; top off.
Check battery level; inspect battery terminals; top off.
Check belt tensions & report if adjustment needed.
Check engine compartment for overall appearance & report.
Lube hood hinges & locks.
Check steering linkages for wear while draining oil & report.
Check exterior lighting; report if any bulbs are inoperative.

Line Total	36.20
Labor	16.50
Parts	19.70
Sublets	0.00

Part Number	Description	QTY	Each	Total
11 12 1 345 223	Oil Filter	1	8.45	8.45
Oil, QT	Castrol GTX 10W50	4.5	2.50	11.25

Demo Motors | 123 Main Street | Anytown, US 00000

Tel: 800-937-4361 | Fax: 978-856-2209 | URL: www.genesisfour.com

Estimates are an approximation of charges to you, and they are based on the anticipated details of the work to be done. It is possible for unexpected complications to cause some deviation from the estimate. If additional parts or labor are required you will be contacted immediately.

Estimate Total	
Labor	\$601.50
Parts	\$411.86
Sublets	\$0.00
Supplies	\$24.06
Subtotal	\$1,037.42
Tax	\$21.27
Total	\$1,058.69